

DENON

Service Bulletin

No. : OST-US005


Date: March 29, 2007

Model: AVR-2307, AVR-2307CI

Subject: Service Manual Part Correction

Symptom: Diodes D101 and D102 (FL, FR, C, SL, SR, SBL and SBR) are shown as 1N4148W. The part list shows a different part name (KDS160) and part number (00D 960 0197 000). This information is incorrect.

Solution: Use the part number listed in the part section when ordering replacement D101, D102 (FL, FR, C, SL, SR, SBL and SBR) diodes.



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by DENON Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the DENON Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by DENON for any damage, injury or loss resulting from the misuse of the information contained in this document.

Parts:

Ref#	Description	Part Number
D101, D102	00D 963 0355 401	KDS4148U

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by DENON Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the DENON Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by DENON for any damage, injury or loss resulting from the misuse of the information contained in this document.