

DENON

Service Bulletin

No. : OST-F1108 **Date:** March 13, 2007

Model: AVR-2307CI, AVR-887

Subject: Countermeasure for XM radio malfunction.

Symptom: Sometimes equipment does not receive XM radio properly with the CNP-1000 type XM Antenna. Malfunction: no indication of the station name, no output and no channel selectable when using XM radio.

Solution: Please install the Exclusive Writer Software to a PC and rewrite your customer's unit upon claim of XM radio malfunction.

- Install Software of the Exclusive Writer Software to be installed to the PC. For AVR-2307CI: "FWCV_AVR2307_V0028_SETUP.exe" For AVR-887: "FWCV_AVR887_V0028_SETUP.exe"
- The Exclusive Writer Software: (After the installation, a short cut of the following Exclusive Writer Software is created on the Desk-top of the PC.)
- To confirm the Version after the update, please refer to the following: For AVR-2307CI: "2307_0028_VERS_CHECK.pdf" For AVR-887: "887 0028 VERS CHECK.pdf"
- The Exclusive Jig (JIG-232C (887)) for the AVR-887.

Detail of XM Antennas: XM Antenna CNP-1000 (old type XM Antenna)



XM Mini Tuner Home Dock CNP-2000H



Serial Number Range:

AVR-2307CI 00001 ~ 05438 AVR-887 00001 ~ 03810

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by DENON Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the DENON Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by DENON for any damage, injury or loss resulting from the misuse of the information contained in this document.