

DENON

Service Bulletin

No. : OST-US014

Date: November 15, 2007

Model: AVR2307CI

Subject: Service Manual Part correction

Symptom: The part number outlined in the parts section for transistor Q502 (276 0844 902) is incorrect.

Solution: Use the corrected part number listed below when ordering a replacement Q502 transistor.

Parts:

Ref #	INCORRECT		CORRECT	
	Description	Part Number	Description	Part Number
Q502 (C, FR, FL, SL, SR, SBL, SBR)	KSA992F	276 0844 902	KSA992F	960 0196 205

Serial Number Range:

All

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by DENON Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the DENON Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by DENON for any damage, injury or loss resulting from the misuse of the information contained in this document.