

# Firmware Release Notes

## Araknis 110 Series Switches

Version 1.0.01



## Release Details

Release Date	4/22/2016
Firmware Version	1.1.01
Product SKUs Affected	AN-110-SW-C-5 AN-110-SW-R-8 AN-110-SW-R-16 AN-110-SW-R-24

## Resolved Functional/Local Issues

- Fixed issue where the switch would not be able to recover to a dynamic IP address in the event it would default to 192.168.20.254. Added 30-second DHCP retries.
- Fixed the blink rate of the LEDs.
- Fixed displayed hostname communicated by the switch.
- Fixed firmware upgrade locally to now have a status, previously would just sit idle until device was fully upgraded.

## Resolved Cloud Issues

- Fixed issue where there would be no connection to OvrC servers as a result of targeting secondary servers. Now always targets primary server for reconnection attempt.
- Fixed issue where the DHCP setting would be defaulted off in the event that a system setting were changed via OvrC.
- Fixed issue where changing port settings via OvrC would cycle the port link status.
- Fixed issue wherein the switch would fall offline as a result of pulling an IPv6 format address for DNS.
- Fixed issue where the switch would reboot after sending any kind of settings change via OvrC.

## Contacting Technical Support

Phone: (866) 838-5052

Email: [support@araknisnetworks.com](mailto:support@araknisnetworks.com)