

DENON

Service Bulletin


No.: OST-C1102 **Date:** March 14, 2007

Model: AVR-2307CI, AVR-2307, AVR-887

Subject: Countermeasure for the AUTO SETUP Phase symptom.

Symptom: Upon execution of the AUTO SETUP the unit indicates the Phase Error message "-Caution- phase" (all channels) even though the speakers have been connected properly.

Solution: If the above complaint was reported from your customer, please explain to your customer the "Cause" and "Measure" of Instruction manual page13. Check the polarity of the pertinent speakers. For some speakers, this screen may be displayed even though the speakers are properly connected. If so, please select "**Skip <** " on the OSD screen from which the error message has been indicated and proceed to the next step." Instruction manual page13:



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by DENON Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the DENON Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by DENON for any damage, injury or loss resulting from the misuse of the information contained in this document.