




## WIRING — DIAGRAM



- LEGEND**
- ATS-AUTOMATIC TRANSFER SWITCH
  - C1-UTILITY COIL & RECTIFIER
  - C2-GENERATOR COIL & RECTIFIER
  - F1, F2-5A, 600V FUSE
  - LC-CIRCUIT BREAKER (LOADS)  
(16 CIRCUIT SHOWN FOR REFERENCE ONLY)
  - N-NEUTRAL
  - TR-TRANSFER RELAY
  - TS-TERMINAL STRIP
  - XA, XB-LIMIT SWITCHES