



Service Bulletin

No. : MZ05-012

Date: January 9, 2007

Model: SR4500

Subject: Correction of the Service Manual Mechanical parts list.

Symptom: The part number in the service manual for the Volume Knob Assembly is incorrect.


Solution: Use the new number listed in the Parts section.

Parts:

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
1	VOLUME KNOB ASS'Y (BLACK)	00M28AW154010	VOLUME KNOB ASS'Y (BLACK)	00M27AW154010
1	VOLUME KNOB ASS'Y (SILVER)	00M28AW154030	VOLUME KNOB ASS'Y (SILVER)	00M27AW154030

CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.



CONFIDENTIALITY NOTICE:

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.