



**Service Bulletin**  
**No. : MZ05-047**  
**Date:** January 3, 2007

**Model:** SR4500

**Subject:** Correction of the Service Manual, Electrical parts list.

**Symptom:** The parts numbers for Q653, Q654, Q655, Q661, Q804 and Q807 outlined in the SR4500 Service Manual are incorrect (on page 91).

**Solution:** Use the part number listed below when ordering replacement parts.

**Parts:**

Ref #	FORMER		NEW	
	Description	Part Number	Description	Part Number
Q653, Q654, Q655, Q661, Q804 and Q807	2SB1560	90M-HT200441R 90M-HT200442R 90M-HT200443R 90M-HT200444R 90M-HT200445R 90M-HT200446R	2SB1560	90M-HT200440R

**Serial Number Range:**

All

**CONFIDENTIALITY NOTICE:**

The information contained in this document is intended for the exclusive use by MARANTZ Authorized Service Centers and their employees. This document may contain information that is privileged, confidential and may be protected from disclosure under applicable laws and terms of the MARANTZ Service Agreement. Any distribution, disclosure, dissemination or copying of this document and the information it contains is prohibited. No responsibility will be accepted by MARANTZ for any damage, injury or loss resulting from the misuse of the information contained in this document.